## (CALL 4801) Vintage - BS 5852: 2006 Source 5 (Clause 11) 24/08/2016

**BV Report Ref:** TR4094/179333

**Submitted By:** CAMIRA FABRICS LTD

MELTHAM MILLS, MELTHAM, WEST YORKSHIRE,

Bureau Veritas

Consumer

Products Services UK Ltd 31 Kingsland

Grange Woolston Warrington

Cheshire WA1 4RW

HD9 4AY - UNITED KINGDOM

Contact Name: ERIN WILSON / REBECCA BROOK

**Order Date:** 9<sup>th</sup> August 2016

**Order No:** 57381

**Date of Receipt:** 10<sup>th</sup> August 2016

Item Description:VintageColour:SeraphStyle No:None StatedEnd Use:None Stated

**Claimed:** 100% Leather with Interliner

**Test Specification:** BS 5852: 2006 – Method of test for the assessment of the ignitibility of

upholstered seating by Smouldering and flaming ignition sources.

Test Details		
Test method(s)	BS 5852: 2006	
Water soak Procedure	BS 5852: 2006 Annex E (Line Dried)	
Conditioning:	72hrs Ambient / Specified $20 \pm 5^{\circ}$ C & $50 \pm 20\%$ rh $\geq 16$ hrs	
Filling used: (36110 CMHR Foam)	BS 5852: 2006 (Source 5)	

**Conclusion(s):** The sample supplied **complies** with the test requirements of BS 5852: 2006

(Clause 11) Source 5

**Note:** The following test results relate only to the ignitability of the combination of

upholstered composites (BS 5852: 2006 Clause 11) under the particular conditions of test; they are not intended as a means of assessing the full potential fire hazard of the

materials in use.

**Authorized By:** Mark Jones **Issue date:** 24<sup>th</sup> August 2016

Head of Flammability





Tests marked 'Not UKAS Accredited' in this report are not included in the UKAS schedule for this laboratory. Opinions and interpretations expressed herein are outside the scope of the UKAS Accreditation. The information contained within any report is based on current BVCPS UK Ltd knowledge and is given without guarantee. A satisfactory test report in no way implies that the product so tested is approved by BVCPS UK Ltd, UKAS or other body. A report is a confidential document to the person or firm to whom it is issued and it will be strictly treated as such by BVCPS UK Ltd. It may not be reproduced either in its entirety or in part and may not be used for advertising. The person or firm to whom the report is issued may however show it or send it, or a certified copy thereof prepared by BVCPS UK Ltd, for the information of his customer, supplier or other persons directly concerned. BVCPS UK Ltd will not, without the written consent of the person or firm, enter into any discussion or correspondence with any third party concerning the contents of the report. In the event of the improper use of a report, BVCPS UK Ltd reserves the right to withdraw it or adopt any other remedy which may be appropriate. Samples submitted for testing are accepted on the understanding that the report issued shall not form the basis of or instrument for, any legal liability against BVCPS UK Ltd and applies specifically to the sample(s) tested and not necessarily to the bulk.

Bureau Veritas Consumer Products Services UK Ltd, Registered in England & Wales, Company Number: 00852439 Registered Office: 31 Kingsland Grange, Woolston, Warrington, Cheshire, WA1 4RW

## (CALL 4801) Vintage - BS 5852: 2006 Source 5 (Clause 11) 24/08/2016

**BV Report Ref:** TR4094/179333

Item Description:VintageColour:SeraphStyle No:None StatedEnd Use:None Stated

Claimed: 100% Leather with Interliner

## **Specimen Results:**

BS 5852: 2006 Clause 11 – Source 5	Initial Test	Repeat Test
Flaming Duration:	4 Min(s) 15 Sec(s)	5 Min(s) 26 Sec(s)
Smoldering Criteria	. ,	. ,
a) Unsafe escalating smoldering combustion?	NO	NO
e) Any detectable amounts of smoke, Heat or glowing 60 Minutes after extinction of the source:	NO	NO
c) Specimen essentially consumed or smolders to extremities including thickness within the duration of the test	NO	NO
a) Unsafe escalating smoldering combustion?	NO	NO
Flaming Criteria		
a) Unsafe escalating flaming combustion.	NO	NO
b) Essentially consumed within the duration of the test	NO	NO
c) Flame front reached extremities and/or full thickness with the duration of the test	NO	NO
e) Flaming continued to burn for more than 10 Minutes after source ignition.	NO	NO
Result	NI/5	NI/5

**Key:**  $NI/5 = No \ Ignition \ source \ 5$